



Veriforce OQs Offered by Basin Safety

Task #	Description
CCT - 004	Inspect and Calibrate Breakout Tank Overfill Protective Devices
CCT - 006	Inspection of Breakout Tanks
SCE - SCE087	Inspect and Repair of Breakout Tanks
CCT - 010	Routine Visual Inspection of Breakout Tanks
CCT - 007	Operate Valves
CCT - 008	Measurement of Wall Thickness with Ultrasonic Device
CCT - 103	Non-destructive Testing (Other than testing of welds) -- Mag Particle
CCT - 201	Abnormal Operating Conditions Related to Welding on Pipelines
CCT - 202	Monitoring of Welding Process
SCE - SCE059	Perform Welding Inspection
CCT - 204	Non-Destructive Testing (Dye Penetrant)
SCE - SCE077	Perform Advanced Liquid Penetrant Testing
DOMHOPE - OQ-0611	Task 0611 NDT - Liquid Penetrant Testing
DOM - OQ-0611	Task 0611 NDT - Liquid Penetrant Testing
CCT - 205	Non-Destructive Testing (Mag Particle)
SCE - SCE076	Perform Advanced Magnetic Particle Testing
DOMHOPE - OQ-0621	Task 0621 NDT - Magnetic Particle Testing
DOM - OQ-0621	Task 0621 NDT - Magnetic Particle Testing
CCT - 103	Non-destructive Testing (Other than testing of welds) -- Mag Particle
CCT - 206	Non-Destructive Testing (Ultrasonic)
SCE - SCE078	Perform Advanced Ultrasonic Testing
DOMHOPE - OQ-0631	Task 0631 NDT - Ultrasonic Testing
DOM - OQ-0631	Task 0631 NDT - Ultrasonic Testing
CCT - 008	Measurement of Wall Thickness with Ultrasonic Device
CCT - 207	Non-Destructive Testing (X-Ray)
SCE - SCE075	Perform Radiographic Testing
DOMHOPE - OQ-0601	Task 0601 NDT - Radiographic Testing
DOM - OQ-0601	Task 0601 NDT - Radiographic Testing
CCT - 213	Joining of Metal Pipe and Components by means other than Welding - Threaded and Flanged Connections
CCT - 215	Joining of Metal Pipe and Components by means other than Welding- Flanged Connections
CCT - 214	Joining of Metal Pipe and Components by means other than Welding - Threaded Connections
CCT - 214	Joining of Metal Pipe and Components by means other than Welding - Threaded Connections
DOM - OQ-0721	Task 0721 Joining of Pipe - Threaded Joints



Veriforce OQs Offered by Basin Safety

Task #	Description
CCT - 215	Joining of Metal Pipe and Components by means other than Welding- Flanged Connections
DOM - OQ-0731	Task 0731 Joining of Pipe - Flange Assembly
CCT - 401	Examination of Buried Pipelines When Exposed
DOMHOPE - OQ-0201	Task 0201 Visual Inspection of Installed Pipe and Components for Mechanical Damage
DOMHOPE - OQ-0151	Task 0151 Visual Inspection of Buried Pipe and Components When Exposed
DOM - OQ-0201	Task 0201 Visual Inspection of Installed Pipe and Components for Mechanical Damage
DOM - OQ-0151	Task 0151 Visual Inspection of Buried Pipe and Components When Exposed
CCT - 406	Conduct Test to Determine Cathodic Protection Current Requirements
CCT - 407	Perform Cathodic Protection Survey
DOM - OQ-0011	Task 0011 Conduct Close Interval Survey
CCT - 419	Cathodic Protection Potential Measurement
CCT - 408	Inspect Cathodic Protection Rectifier
BWP - BWP9028	Inspect Cathodic Protection Rectifier
CCT - 409	Inspect Interference Bonds
SCE - SCE003	Investigate/Correct Interference Problems
DOMHOPE - OQ-0061	Task 0061 Inspect or Test Cathodic Protection Bonds
DOM - OQ-0061	Task 0061 Inspect or Test Cathodic Protection Bonds
BWP - BWP9029	Inspect Interference Bonds
CCT - 410	Clear Shorted Casing
CCT - 411	Inspect/Test to Assure Electrical Isolation is Adequate
SCE - SCE014	Test Electrical Isolation on Flanges/Connections
DOMHOPE - OQ-0071	Task 0071 Inspect or Test Cathodic Protection Electrical Isolation Devices
DOM - OQ-0071	Task 0071 Inspect or Test Cathodic Protection Electrical Isolation Devices
CCT - 412	Install CP Leads on Pipeline Using Exothermic Weld
DOMHOPE - OQ-0051	Task 0051 Installation of Exothermic Electrical Connections
DOM - OQ-0051	Task 0051 Installation of Exothermic Electrical Connections
CEC - CHK-412i	Install CP Leads on Pipeline Using Exothermic Weld (Inspection only)
CCT - 414	Inspect for Internal Corrosion Whenever Pipe is Removed
DOMHOPE - OQ-0161	Task 0161 Visual Inspection for Internal Corrosion
DOM - OQ-0161	Task 0161 Visual Inspection for Internal Corrosion
CCT - 415	Monitoring for Internal Corrosion with Probes and Coupons
SCE - SCE007	Install/Remove Corrosion Coupons and Electronic Probes For Analysis
DOMHOPE - OQ-0131	Task 0131 Insert and Remove Coupons / Probes for Internal Corrosion Monitoring

Task #	Description
DOM - OQ-0131	Task 0131 Insert and Remove Coupons / Probes for Internal Corrosion Monitoring
CCT - 417	Atmospheric Corrosion Monitoring
DOMHOPE - OQ-0141	Task 0141 Visual Inspection for Atmospheric Corrosion
DOM - OQ-0141	Task 0141 Visual Inspection for Atmospheric Corrosion
CCT - 418	General and Localized Corrosion Measurement (Remedial Measures)
CCT - 008	Measurement of Wall Thickness with Ultrasonic Device
CCT - 419	Cathodic Protection Potential Measurement
DOMHOPE - OQ-0001	Task 0001 Measure Structure-to-Electrolyte Potential
DOM - OQ-0001	Task 0001 Measure Structure-to-Electrolyte Potential
BWP - BWP9030	Cathodic Protection Potential Measurement
CCT - 420	Soil Resistivity
DOM - OQ-0021	Task 0021 Measure Soil Resistivity
CCT - 427	Inspection of Coating Application
ETC - ET-427-I	Inspection of the Application of Above or Below Ground Coatings
CCT - 465	Inspect and Maintain Cathodic Protection Rectifier
CCT - 480	Apply Approved Coating by Hand Application
DOM - OQ-0991	Task 0991 Coating Application and Repair - Brushed or Rolled
CCT - 482	Apply Approved Coatings by Mechanical Spray and Hand Application Methods
DOMHOPE - OQ-0991	Task 0991 Coating Application and Repair - Brushed or Rolled
DOM - OQ-1001	Task 1001 Coating Application and Repair - Sprayed
DOM - OQ-0991	Task 0991 Coating Application and Repair - Brushed or Rolled
CCT - 480	Apply Approved Coating by Hand Application
CCT - 484	Apply Approved Coatings by Wrap Application
DOM - OQ-1011	Task 1011 Coating Application and Repair - Wrapped
CCT - 501	Conduct a Pressure Test
DOMHOPE - OQ-0581	Task 0581 Pressure Test - Liquid Medium
DOMHOPE - OQ-0571	Task 0571 Pressure Test - Non-liquid Medium - Test Pressure Greater Than or Equal To 100 psi
DOM - OQ-0581	Task 0581 Pressure Test - Liquid Medium
DOM - OQ-0571	Task 0571 Pressure Test - Non-liquid Medium - Test Pressure Greater Than or Equal To 100 psi
CEC - CHK-501i	Conduct Pressure Test to Substantiate MAOP / MOP (Inspection only)
CCT - 502	Conduct Pressure Test on Pipe that is to be Operated at a Pressure <100 psig
DOM - OQ-0561	Task 0561 Pressure Test - Non-liquid Medium -Test Pressure Less Than 100 psi
CCT - 601	Start-up/Shut-down of Pipeline to Assure Operation Within MAOP / MOP

Task #	Description
CCT - 603	Compressor Units: Startup, Operation, Shutdown and Purging Before Returning to Service
SCE - SCE072	Startup/Shutdown/Operate Station
SCE - SCE066	Start/Stop/Load Drivers and Compressors
SCE - SCE065	Read/Verify/Maintain Operating Parameters on Drivers and Compressors
CCT - 604	Locate, Mark, and Remediate Exposed Pipelines in the Gulf of Mexico
CCT - 605	Locate Line/Install Temporary Marking of Buried Pipeline
CCT - 618	Install Temporary Marking of Buried Pipeline
CCT - 617	Locate Buried Facilities with an Electro-magnetic Device
CCT - 606	Locate and Mark Submerged Pipelines
CCT - 607	Damage Prevention: Observation of Excavating and Backfilling
DOM - OQ-1321	Task 1321 Damage Prevention during Excavation Activities By or On Behalf of the Operator
CCT - 609	Inspect and Maintain Odorization Equipment
DOMHOPE - OQ-1221	Task 1221 Odorization - Odorizer Inspection, Testing, Preventive and Corrective Maintenance
DOM - OQ-1221	Task 1221 Odorization - Odorizer Inspection, Testing, Preventive and Corrective Maintenance
CCT - 610	Monitor Odorant Concentration
DOMHOPE - OQ-1211	Task 1211 Odorization - Periodic Sampling
DOM - OQ-1211	Task 1211 Odorization - Periodic Sampling
CCT - 611	Hot Tap (Steel Pipe)
DOMHOPE - OQ-1101	Task 1101 Tapping a Pipeline with a Built-in Cutter
DOM - OQ-1101	Task 1101 Tapping a Pipeline with a Built-in Cutter
CEC - CHK-611i	Hot Tap (Steel Pipe) (Inspection only)
CCT - 701	Patrolling Pipeline and Leakage Survey without Instrument
DOM - OQ-1311	Task 1311 Inspect Pipeline Surface Conditions - Patrol Right Of Way or Easement
CCT - 702	Leakage Survey with Leak Detection Device
DOMHOPE - OQ-1261	Task 1261 Walking Gas Leakage Survey
DOM - OQ-1261	Task 1261 Walking Gas Leakage Survey
CCT - 703	Placing/Maintaining Line Markers
DOM - OQ-1301	Task 1301 Install and Maintain Pipeline Markers
CCT - 704	Permanent Field Repair by Grinding
DOM - OQ-1071	Task 1071 Repair of Steel Pipe by Grinding
CEC - CHK-704i	Permanent Field Repair by Grinding (Inspection only)
CCT - 705	Permanent Field Repair Using Composite Materials (Clockspring)
SCE - SCE037	Install Composite Repair Sleeve



Veriforce OQs Offered by Basin Safety

Task #	Description
DOMHOPE - OQ-1064	Task 1064 Install Composite Sleeve - Clock Spring
DOM - OQ-1064	Task 1064 Install Composite Sleeve - Clock Spring
CCT - 706	Permanent Field Repair Using Composite Materials (Armor Plate)
CCT - 707	Permanent Field Repair Using Bolt-On Clamp/Sleeve
DOMHOPE - OQ-1041	Task 1041 Install Mechanical Clamps and Sleeves - Bolted
DOM - OQ-1041	Task 1041 Install Mechanical Clamps and Sleeves - Bolted
CCT - 708	Permanent Field Repair Using Full Encirclement Weld Sleeve
DOMHOPE - OQ-1051	Task 1051 Fit-up of Weld Type Repair Sleeve
DOM - OQ-1051	Task 1051 Fit-up of Weld Type Repair Sleeve
CCT - 709	Inspection and Testing of Relief Devices (Compressor Stations, Meter Stations, Regulating Stations)
SCE - SCE055	Test Relief Valve
CCT - 714	Inspect and Maintain Pressure Limiting and Regulating Devices
CCT - 716	Inspect, Maintain, and Operate Valves
SCE - SCE048	Troubleshoot/Repair Valves - Major
SCE - SCE028	Inspect/Operate/Maintain Valves, Valve Actuators, and Operators
CCT - 007	Operate Valves
CCT - 717	Maintaining Vaults With Pressure Regulating and Pressure Limiting Equipment
CCT - 719	Permanent Field Repair Using Composite Materials (Wrapmaster)
CCT - 721	Permanent Field Repair Using Composite Materials (Black Diamond)
CCT - 722	Permanent Field Repair Using Composite Materials (Aqua Wrap)
CCT - 724	Permanent Field Repair Using Composite Materials (PipeWrap A+ / Atlas CFP)
CCT - 725	Aerial Leakage Survey: Transmission
CCT - 762	Line Stopping Utilizing a Hot Tap Fitting
CCT - 902	Field Bending of Pipe
CCT - 909	Data Collection for As-Built Pipe Location Documentation
FCG - FCG JQ-PLS- EFUSE-SDL-04	Plastic Fusion Electrofusion Saddle Fitting 4
FCG - FCG JQ-PLS- EFUSE-SDL-06	Plastic Fusion Electrofusion Saddle Fitting 6
FCG - FCG JQ-PLS- EFUSE-SDL-08	Plastic Fusion Electrofusion Saddle Fitting 8
FCG - FCG JQ-PLS- EFUSE-SDL-12	Plastic Fusion Electrofusion Saddle Fitting 12
TC - TC-427-I	Inspection of the Application of Above or Below Ground Coatings (Inspection Only)